




CUT 40PA



- ✘ DUAL Voltage-1~110V/220V(CUT40PADV)
- ✘ Compact and portable with light weight
- ✘ Weight-Extremely low weight and versatility
- ✘ Protections-Various protections and alarm functions for over-temperature and over-current
- ✘ Pilot Arc Controller-increases cutting capabilities and speed,and improves tip life,
- ✘ Ideal for grid cutting-Accessories-High quality plasma cutting torch and earth clamp.

Light Industrial

DC 1 Phase

Processes

- Air plasma cutting

Optional Accessories

- Earth cable and clamp
- Non HF Cutting Torch



MODEL		CUT 40PA
Power Supply Voltage(V)		1-220/230/240±10%
Frequency(HZ)		50/60
Rated Input Power(KW)		4.6
Rated Input Current(A)		23.4
Duty Cycle(40°C 10min)		50% 40A 100% 40A
No Load Voltage(V)		220
Cutting Current Range(A)		20-40
Severance Cut For Carbon Steel(MM)		≤25
Production Cut(MM)	Carbon steel	≤16
	Stainless Steel	≤18
	Aluminum	≤14
	Copper	≤8
N.W.(KG)/(LB)		4.3 KG/9.5 LB
Dimensions(MM)/(Inch)		420*135*290/16.5*5.3*11.4
Power Factor		0.75
Protection Class		IP23
Insulation Class		F
Cooling		AF

Cutting Power Plasma System

www.crepow.com

CE RoHS

CREPOW®
Welding & Cutting Technology